

Contents

FORWARD	i-ii
ACKNOWLEDGMENTS	iii
1. Tectonic Setting	1-3
Tamao Sato	
2. Surface Deformations and Active Faults	
2.1. Surface Deformation around Budharmora	4-14
Takashi Nakata, Toshikazu Yoshioka, Hiroshi Sato, Toshifumi Imaizumi, Javid N. Malik, George Philip, Ambrish K. Mahajan, and Rama V. Karanth	
2.2. Active Faults	15-32
Javid N. Malik, Takashi Nakata, Hiroshi Sato, Toshifumi Imaizumi, Toshikazu Yoshioka, George Philip, Ambrish K. Mahajan, and Rama V. Karanth	
3. Aftershocks and Slip Distribution of Mainshock	
3.1. Aftershock Observations	33-40
Hiroaki Negishi, James J. Mori, Tamao Sato, Ramesh P. Singh, and Sushil Kumar	
3.2. Slip Distribution of Mainshock	41-45
James J. Mori	
4. Postseismic Crustal Deformation Deduced from GPS Observations	46-50
Kaoru Miyashita, Kathamana Vijaykumar, Teruyuki Kato, Yousuke Aoki, and Chapidi D. Reddy	
5. Outline of Damage Survey	51-55
Hitomi Murakami	
6. Estimation of Macroseismic Intensity	
6.1. Macroseismic Intensity Deduced from the Building Damage	56-63
Yoshiaki Hisada and Kimiro Meguro	
6.2. Estimation of MSK Seismic Intensity by Questionnaire Method	64-70
Hitomi Murakami and Venkataramana Katta	
6.3. Ground Condition Estimated from Microtremor Observations	71-74
Sumio Sawada, Fumiaki Uehan, Yasuhiro Hayashi, and Hiroshi Arai	
7. Building Damage	
7.1. Damage of Reinforced Concrete Structures	75-83
Susumu Kono and Hitoshi Tanaka	
7.2. Damage in Gandhidham	84-88
Yasuhiro Hayashi, Sumio Sawada, Sanjay Pareek, and Yoshiaki Hisada	
7.3. Damage to Masonry Structures	89-100
Kimiro Meguro, Fumiaki Uehan, and Pradeep K. Ramancharla	
7.4. Building Materials and Repair and Strengthening Methods of Earthquake Damaged RC Structures	101-104
Sanjay Pareek, Yasuhiro Hayashi, and Sumio Sawada	
8. Damage to Civil Structures and Liquefaction	105-115
Masanori Hamada, Omer Aydan, and Junji Kiyono	
Appendix	
List of Authors	116-117